



Technical Data Sheet

Pellet Models: 8090, 8091, 8330 Air to Fuel Ratio Adjustment

Combustion Fan Speed Setting

Publish Date: 9/29/2011

RE: In the event of recurring NO PELLET messages, the air to fuel ratio may need adjustment.

PROCEDURE: This text is written to support the *Adjusting the Exhaust Fan Speed* section in the appliance's Owner's Manual.

