

Technical Data Sheet

Clydesdale 8490, 8491 & Morgan 8470 Surround Cap Installation

Accessory Kit # 94-5970610 (Matte)

Accessory Kit # 94-5970659 (Blue/Black)

Publish Date: 4/30/2009

INCLUDED IN KIT:

- 1 – Left Surround Cap
- 1 – Right Surround Cap
- 2 – Magnets

TOOLS REQUIRED:

None

PROCEDURE:

1. Place the caps face down on a smooth surface oriented as illustrated below. Using one magnet per cap, place the magnet on the raised boss in the center of the cap as shown below. The assembly shown below is the right hand assembly.



Photo 1 – Magnet Placed on Boss

2. Place the cap against the surround leg, and gently slide down until the cap rests on the hearth as shown below.



Photo 2 – Surround Cap in Position